

Message

From: Castellana, Ben [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=A5E5385776764CC4B9E1A718B4090A30-CASTELLANA,]
Sent: 7/15/2019 4:33:18 PM
To: Rod.Tobias@WestonSolutions.com
Subject: FW: 210 W. Slauson
Attachments: ATT00001.txt; 210 W Slauson - Figures and Tables - DRAFT.pdf

Hi Rod,

Attached are the preliminary results for the Slauson characterization. Let me know your thoughts. The salient points include soil vapor adjacent to the residence to the south, as well as soil TPHg and benzene exceeding 15 feet in a few places. I'm looking into when the house might get demolished.

Cheers,

Ben

From: Alan Malagon <alanmalagon@bowyerenvironmental.com>
Sent: Thursday, July 11, 2019 2:27 PM
To: Ehe, Robert@Waterboards <Robert.Ehe@waterboards.ca.gov>; Castellana, Ben <castellana.ben@epa.gov>
Cc: Danny Dolan <dannydolan@bowyerenvironmental.com>; Brett Bowyer <brettbowyer@bowyerenvironmental.com>
Subject: 210 W. Slauson

Hello Robert,

Please see the attached draft figures and tables. As shown, SV-2 and SV-3 on the neighboring residential property TPHG and benzene concentrations at 15 feet that are slightly in excess of the screening criteria. Given these result, we would like to collect additional soil samples from these two locations to depths of up to 60 feet. All of the methods and protocols described in the approved workplan will be utilized.

I spoke about this with Ben Castellana already and he is okay with the this approach. Could you please call me or respond to this email to let me know if doing the deeper drilling at these two locations is okay with you as well.

Warm Regards,

Alan A. Malagon, MSE, EIT
Staff Engineer



17011 Beach Boulevard, Suite 900
Huntington Beach, CA 92647
Office: (877) 232-4620
Fax: (714) 494-1912

"Helping to Achieve Business Objectives and Environmental Quality"